


SPARE PARTS LIST



ITEM	QTY	PART NO.	DESCRIPTION
1	1	655024	CMPL. ARMATURE ASSEMBLY
1A	1	307B016B1	FAH - DRILLED
2	1	307C015B1	STATOR RING & BASE ASSEMBLY
2A	2	307B015B3	BASE SECTION
2B	4	307A015A5	BATTLE MIG BRACKETS
3	4	307B020A1	MAIN COILS
4	4	307B017A1	MAIN POLES
5	1	307C015A1	PULLEY COVER - DRILLED
6	1	A-900205-14	BEARING - PULLEY END
7	1	307C019A2	PULLEY COVER BAND
8	1	307C014A3	CMPL. COMM COVER ASSEMBLY
8A	1	307C014A1	COMM COVER - DRILLED
8B	1	910C139A13	CMPL. BRUSH RING ASSEMBLY
8B1	1	910B139A9	BRUSH RING ASSEMBLY
8B2	4	900B57A03	BRUSHES
8B3	4	910A139A14	BRUSH SPRINGS
9	1	307C019A5	COMM COVER BAND
10	1	A-900205-13	BEARING - COMM END
11	1	307B018B1	FAH BAFFLE
12	1	B-100235	TERMINAL BOX
13	1	A-900200-04	CHASE NIPPLE
14	1	A-900180-01	EYEBOLT
15	1	307A025A1	KEY

OPT-5-25-WI351